

**Formosa Plastics Reporting Form Lavaca Bay**

|  |                |
|--|----------------|
| <b>Date:</b>   | <b>Time:</b>   |
| 1 <sup>st</sup> stop: May 30, 2020   | 10:56-11:20 am |
| 2 <sup>nd</sup> stop: May 30, 2020   | 11:49-2:10pm   |
| <b>Observer Name: Diane Wilson</b>   |                |
| <b>Email Address: wilsonalamobay@aol.com</b>   |                |
| <b>Phone Number: 361-218-2353</b>  |                |
| <b>Location (Latitude/Longitude) or Nearest Outfall (if known):</b>  |                |
| <b>Outfall 001 in Lavaca Bay (all photos have longitude and Latitude)</b>  |                |
| <b>May we contact you if we have follow-up questions? YES / NO</b>   |                |
| yes  |                |
| <b>Location Description:</b>   |                |
| <b>Describe where pellets are located: ex. floating in the water, on the shore next to the water, on the shore but more than one foot higher than the water, trapped behind a boom? If they're on the shore, are they within reach of the tide?</b>  |                |
| 1 <sup>st</sup> stop: area known as Poor Boys Bait in Port Lavaca, Tx. Located south of causeway and on west shore of Lavaca Bay.  |                |
| 1(a) powder was in debris next to water on west side of Poor Boys Bait shop. Powder had accumulated in area about 3 feet in diameter. Photo has latitude and longitude   |                |
| 1(b) pellets were scattered on north bank and next to water at Poor Boys Bait area. The area was about 6 feet in length. Photo has latitude and longitude.   |                |
| 2 <sup>nd</sup> stop: area is known as Miller's old shrimp docks. Miller does not own it any longer but Waterkeepers had permission to go into the area that is posted. The area has docks and a wave for boats to be repaired. The area is south of Poor Boys Bait Stand and north of Black Rock. It is on the west side of Lavaca Bay. This area has not been checked by Waterkeepers until today. All photos have longitude and latitude. |                |
| 2 (a-g) pellets and powder were scattered on the road, along the banks, along the debris of the shore, floating in vegetation, on the waves near the area known as Millers shrimp docks. It was a large area to cover, lots of grass that covered pellets, and some areas were accessible to tides but the areas farther up on the bank and on the road are most likely only accessible with high tides or storm influences.                 |                |
| 2(h-i) photos of locations covered.  |                |

|  |
|--|
| <b>Estimated length of shore with pellets:</b>   |
| See above  |
| <b>Description of Observation: pellets/powder? scattered, dense? how many pellets do you estimate are present?</b> |
| See above  |
| <b>Photo(s) Taken: YES / NO</b>  |
| Yes, all photos have latitude and longitude  |
| <b>A copy of this form may be mailed to:</b>   |
| ?????  |

*Please Note: As per Consent Decree (Case 6:17-CV-00047) the Remediation Consultant will be notified by the Monitor and may be notified by members of the public if plastics are detected. **The Monitor and members of the public will fill out this approved form and provide to the Remediation Consultant.** The Remediation Consultant will maintain all records of this notification.*

